

My house: Picture shows the part of the fence and plot washed away.





Drainage excavated by Contractor and abandoned



Picture showing part of the drainage done by me to save my property. Other part already washed away.



My compound and the gully.
Note that the gully has extended
right into my compound.



Picture showing front of my house and part of the foundation exposed by the gully.



My house and the gully erosion site



Exposed foundation of my house



Picture showing personal efforts to save the house.



Another view of the damage done